Printed on: 12/25/2008 6:37:49 AM

PRELIMINARY REPORT			NTSB	ID: DCA09RA01	3		Most Critical Injury:			
			Occur	rence Date: 11/27	7/2008		Investigated By: Foreign			
			Occur	Occurrence Type: Accident						
Location/Time										
Nearest City/Place	State			Zip Code	Local Time		Time Zone			
Perpignan					1546		UTC			
Aircraft Information										
Registration Number	Aircraft Manu	r				Model/Series Number				
Type of Aircraft:				Amateur Built Aircraft?						
Injury Summary:	Fatal	7	Serious		Minor				None	
Revenue Sightseeing Flight: No			Air Medical Transport Flight: No							

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On November 27, 2008 at 16:46 local time (15:46 UTC), an Airbus A320, equipped with International Aero Engines (IAE) V2500 engines, German registration D-AXLA, serial number 2500, impacted the Mediterranean sea during approach to runway 33 at Perpignan Rivesaltes airport (LFMP) in Perpignan, France. The aircraft impacted the sea approximately 7 kilometers from the coastline and is reportedly submerged 30-40 meters below the surface of the water. The French Navy is currently conducting recovery efforts, which include the use of remotely controlled vehicles (ROV).

The Bureau dEnqutes et dAnalyses pour la Scurit de lAviation civile (BEA) of France is investigating the accident. As the state of design for the IAE V2500 engines, the NTSB will send a U.S. Accredited Representative to assist the BEA with their investigation. An NTSB powerplants specialist and representatives from the Federal Aviation Administration (FAA) and IAE will accompany the U.S. Accredited representative as Technical Advisors.

All inquiries concerning this investigation should be directed to the BEA at:

Bureau dEnqutes et dAnalyses pour la Scurit de lAviation civile Btiment 153 Aroport du Bourget 93350 Le Bourget France Website: http://www.bea-fr.org

TRANSO_
National Transportation Safety Board
0 7
PRELIMINARY REPORT
7 *** >
AYIATION

NTSB ID: DCA09RA013

PRELIMINARY REPORT		Occurrence Date: 11/27/2008										
$\mathbf{A}\mathbf{y}\mathbf{i}_{\mathcal{E}_{TY}}$	TIQN		Occurre	Acci	dent		1					
Other Aircraft Involv												
Registration Number		Aircraft Manufacturer				Model/Series Nun				nber		
Accident Information	1											
Aircraft Damage: Destroyed Accide					dent C	Occurred Duri	ng:					
Crew	N	ame				Certificate No.						
Pilot												
2												
3												
4												
5												
6												
Operator Informatio	n		ı									
Name XL Airways Germany				Operator	Desig	esignator Code Doing Business As						
Street Address Ci				ity					State	Zip Code		
-Type of Certificate(s) H	leld: Nor	e										
Air Carrier Operating Co	ertificate(S): Foreign Operati	on									
Operating Certificate:					С	Operator Certificate:						
Regulation Flight Condu	cted Und	er: Non-U.S., Non	-Comme	ercial								
Type of Flight Operations	s Conduc	ted: Flight Test;Nor	n-schedu	ıled; Inter	natior	nal						
Flight Plan/Itinerary												
Type of Flight Plan Filed	d:								_			
Last Departure Point					State	Airpor	t Identifier					
Destination					State	Airport	Identifier	_				
						7 til polit	rachinor					
Weather Information	1											
Investigator's Source:						ility ID:	Observatio	Observation Time (Local):				
Sky/Lowest Cloud Cond	ition:		<u> </u>			Ft.						
Lowest Ceiling:				Ft. AGL	\ \	/isibility:		SM	Altin	neter:	"Hg	
		PRELIMINARY	INFOR	MATION	- SUI	ВЈЕСТ ТО (CHANG	GE			Page 2	

National Transportation Safety Board PRELIMINARY REPORT

NTSB ID: DCA09RA013

PRELIMINARY REPORT			Occurrence Date: 11/27/2008					
AVIATION		Occurrence Type: Accident						
	(Continued from page 2)							
Temperature: °C	Dew Point:	°C V	°C Wind Direction:					
Wind Speed: Kts.	Gusts: K	ts. \	Weather Conditions at Accident Site:					
Administration Data								
Notification From			Date					
BEA								
FAA District Office/Coordinator			Investigator-In-Charge (IIC) Joseph M. Sedor					